


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
**LAND CORNER RECORD**

WEXFORD COUNTY  
T 22 N R 9 W

DESCRIPTION OF CORNER C 1/4 corner Section 23  
 CORNER MONUMENT Set 1"x36" pipe with Cedar Guard Post w/location tag  
 DATE MONUMENT PLACED AND WITNESSED 4-27-71  
 WITNESSES TO CORNER..... 30" triple Oak S 82 E 40.47'



18" Oak S 26 E 105.90'

N-S fence Due W 8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

The center of Section 23 was established at the intersection of the N-S & E-W 1/4 lines, during a retracement survey in this area.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Carl F. Rosen*  
REGISTERED LAND SURVEYOR

12028

DATE

5-4-71

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68