


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

WEXFORD COUNTY
T 22 R 9 W

DESCRIPTION OF CORNER Ctr. corner to Section 35
CORNER MONUMENT Fd. 1/2" pipe over 1 1/4" pipe surrounded by stones.
DATE MONUMENT PLACED AND WITNESSED 4-29-71

WITNESSES TO CORNER..... Power Pole N 51 W 64.50'



12" Maple N 23 E 76.78'

4" Rd in conc. mont. Due S 33'

AND
Cedar post w/location tag Due S 33'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner, being a 1/2" pipe over a 1 1/4" pipe, was recovered by the MSHD in 1966. They recovered the center of Sec. 35 as established by Teed in surveys dated 1881 and 1886.

SURVEYOR'S SEAL

SIGNED

Curt F. Rover
REGISTERED LAND SURVEYOR

DATE

5-6-71

DISTRIBUTION:

12028

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68