Cons. 4047 4/96

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_22 NR_9 W___

	Wexford	COUNTY
DESCRIPTION OF CORNER	Witness corner to 1/4 corner between	een_Sections
DESCRIPTION OF CORNER	MONUMENT_im pipe with 4 brase of	ap, marked
WITNESSES TO CORNER	_	
	7" W. Oak - N 62 W - 116	
	6" W. Oak - 8 38 W - 117	Links
	1/4 corner is 859#E - 178	links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this area. Found Teed's corner as established in 1901 from remains of government BTs. Sites for both government BTs in place and remains of Teed's witness N57W 96 links. Stake point well preserved in water sand and was found by digging. No surface evidence of corner. Corner falls on west edge of presently dry pond, within 4 links of straight line between section corners.

Corner placed and witnessed June 6, 1958.

SURVEYORS SEAL

SIGNED REGISTERED LAND SURVEYOR DATE 6/9/58