

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T...22 NR 9.W...

Wexford COUNTY

DESCRIPTION OF CORNER Meander Corner on E-W 1/4 line of Section 2
on East shore of Long Lake.

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

12" R. Pine - North - 123 links

18" W. Pine - N 67 E - 108 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was established by survey procedure during
a subdivision of Section 2 by Forestry Division survey crew.
See survey of Section 2.

Corner was placed and witnessed June 27, 1958.

SURVEYORS SEAL

SIGNED

Francis J. Ostling
REGISTERED LAND SURVEYOR

DATE 7/2/58