

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 22 . . NR. 9. W . .

----- Wexford ----- COUNTY

DESCRIPTION OF CORNER . . Section corner common to Sections 4-5-8-9 . . . . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . . . .

WITNESSES TO CORNER . 14" Double B. Oak . . . . . N 59 E . . . . . 24 links

R. R. rail at fence corner . . West . . . . . 130 links

-----  
-----  
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Found a  $\frac{1}{2}$ " iron pipe and old post in fence line, presumably by Teed in 1901. Teed's witness stumps in place, and SE government BT. Site NW for government BT.

Corner placed and witnessed August 29, 1958.

SURVEYORS SEAL

SIGNED *Kenneth J. Otting* . . . . . DATE 9/16/58 .  
REGISTERED LAND SURVEYOR