

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 22. NR. 9 W.

-----Wexford----- COUNTY

DESCRIPTION OF CORNER .. Section corner common to sections 8-9-16-17 ..

DESCRIPTION OF CORNER MONUMENT .. Left 3/4" pipe in place ..

WITNESSES TO CORNER .. Road Sign Post .. N 2° W .. 21 Links ..

Corner fence post .. S 47 E .. 75 Links ..

14" Boulder .. S 23 W .. 60 Links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Found a 3/4" pipe at trail intersection set by unknown surveyor. Could not identify government BT's but corner appeared to be acceptably located with reference to occupation and by measurement to other corners so was accepted and used in this survey.

Corner was witnessed 9/15/58.

SURVEYORS SEAL

SIGNED *Kenneth J. Ostling* DATE 9/18/58
REGISTERED LAND SURVEYOR