

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 22 NR. 9 W. . . .

Wexford COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 5 and 6

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

8" Aspen - N43E - 8 links

18" W. Pine stump - N38W - 61 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this area. Found 3/4" pipe at corner with evidence of old stake below. Stump in place for probable SW government BT. Only 5 links out of line between section corners. Probably restored by Teed, but unrecorded. Falls at NE corner of new pine plantation.

Corner was placed and witnessed April 22, 1959.

SURVEYORS SEAL

SIGNED Kenneth J. Ostling DATE 4/23/59
REGISTERED LAND SURVEYOR