


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

WEXFORD COUNTY
T 22 N R 9 W

DESCRIPTION OF CORNER SE Cor. of North 24 Rods of SE $\frac{1}{4}$ of NW $\frac{1}{4}$ of Sec. 23
CORNER MONUMENT Set 1"x36" pipe and Cedar Guard Post w/location tag
DATE MONUMENT PLACED AND WITNESSED 4-27-71
WITNESSES TO CORNER..... 20" Oak N 22 W 53.9'



18" Maple N 47 E 22.5'
N-S fence Due W 16'
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

SE cor. of North 24 Rods of SE $\frac{1}{4}$ of NW $\frac{1}{4}$ of Sec. 23.

This corner was established per description while making a retracement survey in this area.

Cor. No. 5 (of Sec. 23) N 00° 11' W 396.00'
Cor. No. J-8 (Ctr. of S 23) S 00° 11' E 921.45'

SURVEYOR'S SEAL

SIGNED

Carl F. Roer
REGISTERED LAND SURVEYOR

DATE

5-4-71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

12028