

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

WEXFORD COUNTY


T 22 N R 9 W

DESCRIPTION OF CORNER Sec. corner common to Secs. 27-28-33-34

CORNER MONUMENT Found 1" pipe in Monument box in approx. intersection  
of roads N-S.E.W.

DATE MONUMENT PLACED AND WITNESSED 4-30-71

WITNESSES TO CORNER..... Power Pole S 37 E 40.25'



Ctr. of 12' CMP Due N 129'

Str. of 12' CMP Due W 126'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner, being a 1" pipe in monument box, was recovered by the MSND in 1964,  
and is a corner of long acceptance and use. Probably originally restored by Teed.

SURVEYOR'S SEAL

SIGNED

*Carl F. Rozer*

DATE

5-6-71

DISTRIBUTION:

REGISTERED LAND SURVEYOR

12028

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68