STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

WE	XFORD		c	OU	YTY
т	22	N	R.	9	¥

			_		
DESCRIPTION OF COR	NER 1/4 corper common to	1/4 corper common to Sections 25 & 36			
CORNER MONUMENT _	Set Standard Dept. Mc	n & Cedar Guard Post			
DATE MONUMENT PLAC	ED AND WITNESSED	4-29-71			
WITNESSES TO CORNE	R 9" Oak	S 26 W	14.0*		
N I	10" Oak	N 81 W	57.01		
25	14" R. Pine	N 83 W	84.01		
	AND E-W Random E-W fence remains	Due N	4.9 ¹ 6.0 ¹		

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found both USBTs as stumps with partial lower faces still showing. Used same to restore 1/4 corner.

SURVEYOR'S SEAL

SIGNED

 $\sqrt{}$

5-6-71

DISTRIBUTION:

REGISTERED LAND SURVEYO

12028

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047 Rev. 10/68