

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

WEXFORD COUNTY


T 22 N R 9 W

DESCRIPTION OF CORNER 1/4 corner common to Sections 27 - 28

CORNER MONUMENT Found 1 1/2" pipe, buried 1 ft.

DATE MONUMENT PLACED AND WITNESSED 4-30-71

WITNESSES TO CORNER..... Power Pole S 85 E 33.20'



6" Apple N 16 W 42.40'

Cedar post & location tag Due E. 33'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner, being a 1 1/2" pipe was recovered by the NSHD in 1964, and is a corner of long acceptance and use. Probably originally restored by Teed.

SURVEYOR'S SEAL

SIGNED

Carl F. Raer
REGISTERED LAND SURVEYOR

DATE

5-6-71

DISTRIBUTION:

18028

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68