LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 22 N., R. 9 W.	J-2;J-3;
2. PROPERTY CONTROLLING IN SECTION 2	,T. 22 N., R. 9 W.	8;
3. MISCELLANEOUS PROPERTY IN SECTION 2	,T. 22 N., R. 9 W.	2141'-W of J-2

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 27, 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on DECEMBER 27, 19 85, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (Continued):

8

Fd ½" re-rod on top S. side hill; added cedar post w/loc tag

12" Red Oak	N50°W	17.9'
8" Maple clp(4)	N20°E	28.2'
8" Maple	N80°E	35.3'

2141'-W of J-2

Drove 5/8" x 34" re-rod w/RLS cap; set cedar post w/loc tag

6" White Pine	N40°E	31.4'
13" White Pine	N85°E	41.5'
7" White Pine	S70°E	62.6'
E'ly edge lake	Due W	47'± 2'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

J-2 - Previous Dept. corner of Record (K.J.O.-1958). Center of Section 2 at intersection of one-quarter line's.

J-3 - Previous Dept. corner of Record (K.J.O.-1958). Fits D.E. Teed survey dated Nov. 1901. D.E. Teed had Gov't. wit. cor. to west.

8 - Fd. 1/2" rerod for SE Cor. of W½ of frl. NW¼ of Section 2 (SE cor. of Gov't. Lot 4). Previous Dept. Cor. of record (K.J.O.-1958).

2141'-W of J-2 - Meander corner on E-W ¼ line of Sec. 2 on east side of Long Lake. KJO (1958) monument gone. Restored on line across fd. 1/8 Cor. & ctr. of Sec. 2 to East & at prorated distance to KJO West of ctr. of Sec.2 (N89°43'32"W, 2140.96).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-2

Fd. Dept. Mon.; added Cedar post

14" White Oak	N20°W	5.0'
15" Red Oak	S70°E	20.8'
20" White Oak	S20°W	22.4'

J-3

Fd. Dept. Mon.; added cedar post

5" Red. Pine (clp 2)	N20°W	112.7'
16" Red Oak	N20°E	134.5'
14" White Pine	S60°E	143.8'
Dept. Mon. (wit.cor.)	N89°23'W	117.6'

SIGNED BY Carl F. Roser 01-24-86 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ WEXFORD COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET