LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 22 N., R. 9 W.	F-2; F-3;
2. PROPERTY CONTROLLING IN SECTION 4	,T. 22 N., R. 9 W.	9
3. MISCELLANEOUS PROPERTY IN SECTION _____	,T. _____ N. S., R. _____ E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 8, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (Continued):

9

Found 3/4" pipe by Teed

10" Maple	N80°E	41.34'
3" Oak	S46°E	37.98'
18" Oak	S06°E	18.53'
Ctr. U.S. 131	West	42.5'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-2 - Fd. 1" iron pipe as established at intersection of ¼ lines by Co. Surveyor D.E. Teed, June 3, 1901. Corner is in line with old fn. E-W & old abandoned N-S road grade to south. Present N-S winding gravel road is 90'± west.

F-3 - Previous Dept. cor. (1958) of Record (1" pipe with 4" brass cap) per Teed (1901). Stake point fd. that fit Teed N.B.T. stump's & NE Govt. B.T.

9 - Recovered SE corner of SW¼ of NE¼ of Sec. 4 (3/4" iron pipe) as set by Co. Surveyor D.E. Teed, June 3, 1901; mid-way & on line between the ctr. & E¼ cor. of Sec. 4.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-2

Fd. 1" pipe; added 5/8" x 34" rerod w/RLS cap & set ced. post w/loc tag

9" Apple	N04°E	15.41'
26" Maple	N88°W	22.25'
18" Maple	S46°W	24.80'
28" Maple	S10°W	45.27'

F-3

Fd. Dept. Mon. & ced. post; added new cedar post

Power Pole	S58°W	6.92'
10" Twin Maple	N84°E	70.91'
5" P. Pine	S50°E	71.62'
Ctr. old U.S. 31 (gravel road)	West	150'±

SIGNED BY Carl F. Roser 01-24-86 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Wexford County

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET