

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>22</u> N. <u>9</u> R. <u>9</u> W. <input checked="" type="checkbox"/>	<u>K-3;K-5;</u>
2. PROPERTY CONTROLLING IN SECTION <u>12</u>	T. <u>22</u> N. <u>9</u> R. <u>9</u> W. <input checked="" type="checkbox"/>	<u>4;8</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ R. _____ E. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 9, 1986, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**C. (Continued):**

<p style="text-align: center;"><u>4</u></p> <p>Set 3/8" x 36" pipe w/RLS cap &amp; set cedar post w/loc tag</p> <table border="0"> <tr><td>6" Maple</td><td>S84°W</td><td>15.4'</td></tr> <tr><td>8" Twin Red Oak</td><td>N10°W</td><td>6.4'</td></tr> <tr><td>21" Red oak</td><td>S16°E</td><td>13.4'</td></tr> </table>	6" Maple	S84°W	15.4'	8" Twin Red Oak	N10°W	6.4'	21" Red oak	S16°E	13.4'	<p style="text-align: center;"><u>8</u></p> <p>Drove 5/8" x 34" rerod w/RLS cap &amp; set cedar post w/loc tag</p> <table border="0"> <tr><td>10" Black Oak (clp 2)</td><td>N55°W</td><td>11.8'</td></tr> <tr><td>14" White Oak (clp 2)</td><td>N5°E</td><td>8.2'</td></tr> <tr><td>29" White Oak</td><td>S80°E</td><td>39.4'</td></tr> <tr><td>3/8" Pipe Set</td><td>N89°54'W</td><td>164.93'</td></tr> </table>	10" Black Oak (clp 2)	N55°W	11.8'	14" White Oak (clp 2)	N5°E	8.2'	29" White Oak	S80°E	39.4'	3/8" Pipe Set	N89°54'W	164.93'
6" Maple	S84°W	15.4'																				
8" Twin Red Oak	N10°W	6.4'																				
21" Red oak	S16°E	13.4'																				
10" Black Oak (clp 2)	N55°W	11.8'																				
14" White Oak (clp 2)	N5°E	8.2'																				
29" White Oak	S80°E	39.4'																				
3/8" Pipe Set	N89°54'W	164.93'																				

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- K-3 - Previous Dept. Corner of Record (KJO-1958).
  - K-5 - Previous Dept. corner of record (KJO-1958).
  - 4 - Drove 3/8" x 36" pipe for SW corner of NE $\frac{1}{4}$  of NW $\frac{1}{4}$  of Section 12.
  - 8 - Drove 5/8" x 34" rerod for SW corner of SE $\frac{1}{4}$  of NW $\frac{1}{4}$  of Section 12.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<p style="text-align: center;"><u>K-3</u></p> <p>Fd. Dept. Mon.; added cedar post</p> <table border="0"> <tr><td>9" White Oak</td><td>N5°W</td><td>12.8'</td></tr> <tr><td>17" White Oak</td><td>N80°E</td><td>19.5'</td></tr> <tr><td>16" Red Oak</td><td>S15°E</td><td>12.1'</td></tr> <tr><td>5" Maple (clp 2)</td><td>N80°W</td><td>13.1'</td></tr> </table>	9" White Oak	N5°W	12.8'	17" White Oak	N80°E	19.5'	16" Red Oak	S15°E	12.1'	5" Maple (clp 2)	N80°W	13.1'	<p style="text-align: center;"><u>K-5</u></p> <p>Fd. Dept. mon.; added cedar post</p> <table border="0"> <tr><td>14" Red Oak</td><td>N35°W</td><td>42.0'</td></tr> <tr><td>9" Red Oak</td><td>N40°E</td><td>12.0'</td></tr> <tr><td>12" Red Oak</td><td>S75°E</td><td>32.6'</td></tr> <tr><td>14" Red Oak</td><td>S45°W</td><td>11.9'</td></tr> </table>	14" Red Oak	N35°W	42.0'	9" Red Oak	N40°E	12.0'	12" Red Oak	S75°E	32.6'	14" Red Oak	S45°W	11.9'
9" White Oak	N5°W	12.8'																							
17" White Oak	N80°E	19.5'																							
16" Red Oak	S15°E	12.1'																							
5" Maple (clp 2)	N80°W	13.1'																							
14" Red Oak	N35°W	42.0'																							
9" Red Oak	N40°E	12.0'																							
12" Red Oak	S75°E	32.6'																							
14" Red Oak	S45°W	11.9'																							

SIGNED BY Carl F. Roser 01-24-86 DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028


FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

WEXFORD COUNTY