

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>23</u> N. R. <u>9</u> W.	G-12 K-7    K-8
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. S., R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 11-27 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

- G-12      Reestablished corner per standard B.L.M. instructions.
- K-7      Accepted corner as recovered.
- K-8      Reestablished corner per Standard B.L.M. instructions.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

G-12	K-7	K-8
Set DNR Mon & Cedar Guard Post	Fd 1 1/2" pipe in Mon, Box in B.Top road intersection	Set DNR Mon. & Cedar Post
14" ea Trpl Oak S71W 69.2'	Tel.Pole N33E 82.71'	16" Oak N27W 36.9'
6" R.Pine N88E 55.2'	Tel.Pole S37W 45.48'	9" Oak S87E 48.5'
7" R.Pine S49E 92.5'	36" Maple S62E 48.00'	12" Oak S44E 12.0'
	In Ctr.Line Rds. N-S-E-W.	Ctr.line N-S
		Trl rd Due E 17'
		E-W wire in Trees
		Due S 5'


SIGNED BY Carl F. Roser DATE 1-11-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_