LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 23 N., R. 9 W.	K-12 L-11
2. PROPERTY CONTROLLING IN SECTION 36	T. 23 N., R. 9 W.	Code 2
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram — over) were, in a field survey on 11-22 19 72, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-12 Reestablished corner per standard B.L.M. instructions.

L-11 Reestablished corner per standard B.L.M. instructions.

Code 2 Established corner per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-12			L-11			Code 2		
Set DNR Mon & Cedar Gd Post			Set DNR Mon & Cedar Gd. Post			Set 1"x36" pipe & Ced Post w/loc tag		
30" W.P. stp	S76E	32.1'	8" Maple	N 1W	34.9'	5" Cedar	N14W	25.4'
14" Oak	N30E	39.7'	10" Maple	S56W	24.9'	6" Cedar	S74E	80.6'
8" Oak	N46W	76.9'	6" Maple	S 3E	3.5'	5" Cedar	S 8W	43.4'
24" W.P. stp	S22W	49.1'	E-W Rand	Due S	0.5'	E-W Rand Due S		0.75'
N-S Rand	Due W	12'						

SIGNED BY Carl F. Roser DATE 1-11-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

STATE OF CARL F. ROSER LAND SURVEYOR SEAL No. 12028

Form [illegible] FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION JAN 28 1971