STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

		MENTORD	COUNTY
		T <u>28 N</u>	R <u>9 W</u>
DESCRIPTION OF CORNER	ION OF CORNER N 1/16 corner on N-S 1/4 line of Section 28		
CORNER MONUMENT	Set 1"x86" pipe as	d Cedar Guard Fost w/loc	ation tag
DATE MONUMENT PLACED AND	WITNESSED	4-27-71	
WITNESSES TO CORNER	•		
N	24" Oak	S 27 W	20.71
28	24" Oak	N 40 W	64.81
	AND		
CIRCLE CORNER REGISTER	ÆD		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established equidistant and on line between Section corner to North and Center of Section to South, while making a retracement survey in this area.

SURVEYOR'S SEAL

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing