COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1993 DEC 29 AM 9: 43

Linker Low boullens

| For | corners | in | |
|-----|---------|----|--|

Private Claims _

| Wexford (County) | | Located In: | Corner Code ## | WEXFORD COUNTY, MI | | | |
|---------------------|----------------------|-----------------|----------------|---------------------------------------|--|--|--|
| | | | | REGISTER OF DEFOS | | | |
| 1. | Public Land Survey | T 23N R 9W | M-12 | | | | |
| | | T R | | | | | |
| | | T R | | | | | |
| | | T R | | | | | |
| 2. | Property Controlling | S T R | | | | | |
| | in Section | S T R | | | | | |
| 3. | Miscellaneous | S T R | | Register of Deeds Stamp & File Number | | | |
| | Property in Sec. | S | | negister of seeds stamp at the humber | | | |
| 4. | Lot No | , Recorded Plat | | | | | |

Richard Wilcox , in a field survey on November 11 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

| | <u> </u> | 8 | С | D | E | F | G | Н | J | K | L | M |
|----|----------|---------|----------|----------|-----|----------|------------|----------|--------|-----|-----|----------|
| 2 | | 6— | | | | <u> </u> | | | | , | | |
| 3 | L | Ľ | | Ĭ | | <u> </u> | | اً ا | | | | |
| 4 | Ŀ | 7 | L | 8— | L |] 9 — | L., | [| | 1 | 1 | |
| 5 | _ | Ĺ | | Ĭ_ | | <u> </u> | L. | <u>Ľ</u> | Ĺ | | | Ĺ |
| 6 | L, | 8 | L | | L., | 6 | <u> </u> | 5— | ! 1 | 4 | _, | 3— |
| 7 | _ | Ĺ | <u> </u> | Ϊ | | _ | | Ĺ | | | | Ĺ |
| 8 | 1 | 9— | L, | 20 | Ļ | !1— | 2 | 2— | 2 | 3—- | | 4 |
| 9 | | Ĺ | Ŀ | Ĺ | | L | | | | | | _ |
| 10 | L | 30 | L, | 29 | | 28— | L_2 |] 27— | _2 | 6— | 2 | 5— |
| 11 | _ | | ┖ | | 1 | | <u> </u> | | | | | <u> </u> |
| 12 | Ŀ | } 31 | Ļ, | 32— | Ļ | 3— | — 3 | 4 | 3 | 5 | L_3 | 64 |
| 13 | L | <u></u> | L. | <u> </u> | L | <u></u> | <u> </u> | <u></u> | Ш | | | <u> </u> |

- Description of original monument and accessories and/or subsequent restoration:
 - M-12) 1838 GLO Quarter Section post by John Brink, Deputy Surveyor, Y. Pine 16" S 70° W 18, Hemlock 10" N 1°W 57
 - M-12) 1973 Roser survey in Section 36: 1 1/4" x 9" pipe and Cedar post w/ loc. tag, 18" W. Pine S 65° W 59.2', 18" W. Pine N 65° W 45.6', 12" W. Pine N 50° W 58.9', ctr. dirt trail rd. (on curve) N 50° E 37'
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - M-12) 1/4 Section corner common to Sections 36 and 31, T23N, R8W Found 1 1/4" pipe w/ loc. marker ± 51 ' West of centerline of road and ± 47 ' Southwest of centerline of same road. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Peer Group Reviewed and Approved

Willey Richard D. Wilcox, Waxford County Surveyor


- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - M-12) Set 5/8" x 36" Iron with Wexford Co. brass cap stamped: E 1/4, 36 PS 33898, 1993

S 66° W - 59.68 - 26" White Pine N 72° W - 46.35 - 18" White Pine N 48° W - 59.15 - 12" White Pine

N 50° E - 43.00 - Centerline of trail

N 15° W - 8.57 - 2" Maple

S 10° E - 40.98 - 5" Fir



Signed by

Luhry

Date 11/29/93

Surveyor's Michigan License No. 33989