

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 23 N.R. 10 W.  
T. 24 N.R. 10 W.


Wexford COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 4 - 5 - 32 - 33

CORNER MONUMENT left iron in place--set 1/2" bar on top to surface

DATE MONUMENT PLACED AND WITNESSED May 1, 1963

WITNESSES TO CORNER.....



12" H. Maple S 10 E 116.3'

18" H. Maple S 71 W 89.3'

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This corner was found while making a survey in this township. Found large piece of iron (unidentifiable) at corner, at intersection of road E - W - N - S. Appears acceptable as proper location for corner.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE June 21, 1963  
REGISTERED LAND SURVEYOR # 10068