SURVEY & **REMONUMENTATION**

APR 2 5 1995

LAND CORNER RECORDATION CERTIFICATE

RECEIVED

1994 DEC -9 PM 2: 58

	corners	CO	M	VII.	SS	ON
For	corners	în 🐃				

Filing Requirement of Act 74, Mich. P.A. 1970

10 . 1 . 1 1

₩	EXFORD _(County)	Located In:	Corner Code ##	Yender Kongstmiller WEXFORD COUNTY, MI REGISTER OF DEEDS
1.	Public Land Survey	T <u>23N</u> R <u>12W</u> T R T R T R	M-6	
2.	Property Controlling	S T R		
	in Section	S T R		
3.	Miscellaneous	\$ T R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		
4.	Lot No ,	Recorded Plat		A B C D E F G H I J K L
5.	Private Claims			
				· 6-+ 5-+ 4-+ 3-+ 2-+ 1-
				╗╏┈╏═╂┈╏┈┩┈╏┈╏┈╏┈╏┈ ┼ ┈╏┈ ┼ ┈╏┈

CRAIG J. PULLEN , in a field survey on ___ JUNE 21 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 11 12
- Description of original monument and accessories and/or subsequent restoration:
- 1838 GLO SURVEY BY J. BRINK, WOOD POST SUGAR 13 S24W 11 BEECH 7 N16W 30
 - J. ERICKSON PS #16929 FOUND 1" IRON, ACCEPTED AS E½ CORNER. N35°W 56.10' 12" MAPLE N45°E 51.47' T. POLE S35°W 53.74' 7" MAPLE
 - 1977 F. THOMPSON PS #21996 L.C.R.C. L.3 P.140 AND WILCOX SURVEY L.1 P.539 FOUND 1" PIPE, SET WEX. CO. MON. WITNESSES SAME AS 1973.
 - 1982 J. GAVIN PS #21568 L.C.R.C. L.3 P.268 FOUND WEX. CO. MON. TRIPLE 6" TO 12" MAPLES \$70°W 76.31' 14" MAPLE N20°W 67.78' T. POLE N45°E 51.35'
 - 1986 WILCOX ASSOC. PS #14102 SURVEY L.2 P.196 WEXFORD COUNTY MONUMENT WITNESSES SAME AS 1973
 - 1993 WILCOX ASSOC. SURVEY L.72 P.247 J.D. GEERS PS #33977 WEXFORD COUNTY MONUMENT S50°E 63.95' CTR PHONE RISER #C262 \$32°W 61.62' COR. FEN. POST \$47°W 50.72' 4" MAPLE N22°W 85.12' 6" MAPLE
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-6 FOUND WEXFORD COUNTY MONUMENT IN GOOD CONDITION AND 4 PREVIOUS WITNESSES IN CENTERLINE NORTH, SOUTH, EAST, WEST ROADS. THIS CORNER IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER, BEING THE 1/4 CORNER COMMON TO SECTION 13, T23N, R12W, AND SECTION 18, T23N, R11W.

Peer Group Reviewed and Approved Willel

Richard D. Wilcox, Wexford County Surveyor

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-6 EAST ¼ CORNER, SECTION 13, T23N, R12W WEXFORD COUNTY MONUMENT S42°E **CORNER FENCE POST** 52.50 S30°W **CORNER FENCE POST** 61.68 N22°W 6" MAPLE 85.12 543°W 4" MAPLE 50.72 \$53°E **CENTER PHONE RISER** 63.95

OF MICHIGAN CRAIG J. **PULLEN PROFESSIONAL** 3900 AROFESSION SHAVEYOR

04 PAGE 300

Date NOVEMBER 22, 1994

39095 Surveyor's Michigan License No. __