JAN 1 7 1996

## AND CORNER RECORDATION CERTIFICATE

#MICCIANFiling Requirement of Act 74 Mich PA 1970

1995. DEC 14 PM 3: 50

For corners in Wexford (County)	Located In:	Corner Code #	<b>.</b>	674	WEX	ั้งได้ กิดเลิก	May Ve <sup>o</sup> C	alaca OUN	EE.	مسرن 13	
(Oddiny)					RE	มริธั	ir j	LOF	EDS	.!	
Public Land Survey	T R	M-13									
	T R T R										
<ol><li>Property Controlling in Section</li></ol>											
3. Miscellaneous	S T R										
Property in Section			Register	of [	eed	s Sta	mp ·	& File	Nu	mbe	r
4. Lot No	, Recorded Plat			4 5	^		_				
				<u> </u>	Ť	D E	╁	G P	+	<del>-</del>	-
			2	6- 	+	•	-4-	<del>    3</del>	-	-2 	<u>├</u> -
			3				0-	10		-11	12-
George D. Smi	ith, in a field survey onDecem	ber 7 19 95	. 5							1	ــــــــــــــــــــــــــــــــــــــ
	er requirements of P.A. 74, Michigan P.A. o			18.	L_		 -16		[	\	
	in conformance with regulations and rule	•	***	10		ľΤ	-16	Τï			
	tions of the United States Department	•									
	ee of a Court of Law and/or that the corne			19- 		20	-21 — l	22	$\dashv$	-23	24-
	ance with the rules of the Michigan Board established, re-established, monumented			-	╅	<del>   </del>		+	-		┼┼
as expressed below:	ostabilotion, to ostabilistica, monantened	, to monumented, tooovered,	10	30		9	28-	27	+	-26	25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded					-		-	+		-	
on this certifica	te.		12	31-	十;	2	33 	34		-35 	36-
A. Description of orig	inal monument and accessories and	or subsequent restoration	n:								
1837 GLO 6 mil	e post by John Brink, Deputy Surveyo	r. Birch 10 S 53 1/2°E 11. 1	Famarack 10 N	270	W 42	,					
1893 Devoe Surv	ey for Petition in Section 6, T22N-R10	W Liber 1 Page 175 found	d large nost un	 ler c	rocci	an Ior	· aiv	foot.			

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

in mud, old Tamarack witness was there but nearly decayed, Birch 8, S 35°E 44

Computed location of Township comer, by double proportionate measure between fd. SE cor. Section 13, T23N-R11W, and found E 1/4 Section 1, T22N-R11W, found South 1/4, Section 31 T23N-R10W and found South 1/4, Section 36 T23N-R11W. This computed location which checks closely with Devoe distances to East and South falls in water ±3 deep and is ±4 East of centerline old road South and ± 20' North of old sunken road East-West, and position of Township corner which was not set is accepted as a careful and faithful re-establishment of the position of the original corner, being the Township cor. common to T23N-R11W T22N-R11W, T23N-R10W and T22N-R10W. Set witness corner on East line Section 1, T22N-R11W 40.00' South of Township corner, and 200' North of Township corner on East line Section 36, T23N-R11W.

> Peer Group Reviewed and Approved ul DWlys Richard D. Wilcox, Wexford County Surveyor

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<del>39398</del>

Witness Corner on East Line Section 36, T23N-R11W, set 5/8" x 36' iron with Wexford County brass cap stamped: Wit. cor. 1995, PS 39098, ±15' West of centerline old sunken road N 3° E 34.35' 8" Maple S 70° W 18.10' 5" Y. Birch MICHIGAN N 47° E 45.62 5" Ironwood N 85° W 30.55' 6" Maple S 01°37'15" E 200.00 computer Fownship S 87°00'43" E 2670.02' CECHOW D. S 1/4 S 83°14'26" W 2619.67 S T23N4R1HW PROFESSIONAL <del>SUAVEYO</del>II

Witness Corner on East Line Section 1, T22N-R11W, set 5/8" x 36" iron with Wexford County brass cap stamped: Wit. Co. 1995, PS 39098, ±5' East of centerline old road. S 74° W 20.45 7" Elm S 34° W 56.401 14" Maple 8" Maple S 12° E 44.55' S 50° W. 65.78' 6" Apple

N 01°59'50" W 40.00' Computed loc. of Township cor. S 88°29'49" W 2609.41 S 1/4 Sec. 36, T23N-R11W N 87°49'52" E 2661.24 S 1/4 Sec. 31, T23N-R10W

Date 12-14-95

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JA REVISED JAN., 1983

Surveyor's Michigan License No.