


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

WEXFORD COUNTY  
T 20 N R 9 W

DESCRIPTION OF CORNER East 1/4 corner, Section 20  
CORNER MONUMENT Added BNR Monument (buried).  
DATE MONUMENT PLACED AND WITNESSED 10-8-71  
WITNESSES TO CORNER..... 14" Maple S 89 W 99.1'



32" Oak S 29 E 113.4'  
10" R. Pine N 52 E 60.9'  
AND Set Cedar Post & Lee Tag Due W 33'  
Dirt Road to East Due N 15'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**Found 2" pipe in Concrete (Schanz Corner) as recovered & witnessed by M.S.H.D. in 1957. Corner is in line with old fence to East and falls in N-S dirt road.**



SURVEYOR'S SEAL

SIGNED

*Carl F. Roser*  
REGISTERED LAND SURVEYOR

DATE

10-15-71

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68