


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

WISCONSIN COUNTY  
T 24 N R 9 W

DESCRIPTION OF CORNER West 1/4 Corner, Section 15  
CORNER MONUMENT Added D.N.R. Monument & Cedar Post  
DATE MONUMENT PLACED AND WITNESSED 10-6-71  
WITNESSES TO CORNER..... 9" Maple (in cluster) S 19 W 80.8'



9" R. Pine S 51 E 109.9'  
9" R. Pine S 72 E 100.6'  
AND  
Ctr. N-S Dirt Road Due E 29'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**Recovered Fargo Corner (3/4" pipe) as recovered and witnessed by N.S.N.D in 1967; in line with center of dirt road to East.**



SURVEYOR'S SEAL

SIGNED Carl F. Roser DATE 10-15-71  
REGISTERED LAND SURVEYOR **12028**

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68