## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 24 N. R. 9 W.	K-7; L-9; M-7; M-9	
2. PROPERTY CONTROLL- 24 ING IN SECTION	, <sub>T.</sub> 24 N. 9 W.	2	
3. MISCELLANEOUS PROPERTY IN SECTION	,T		
4. LOT NO, REC	ORDED PLAT		
5. PRIVATE CLAIMS		· · · · · · · · · · · · · · · · · · ·	REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in l re-established, monumented, re- and rules therefore as required Bureau of Land Management or and 5 above were, in a field surv	ines 1 and 2 above were, in a monumented, recovered or r in the current manual of surv by a decree of a court of law ey on	n field survey onJanuary estored as expressed below and vey instructions of the United S v. Furthermore, that the corner ., 19, found, recovered, rest	of P.A. 74, Michigan P.A. of 1970, 26, 1981, established, in conformance with regulations states Department of the Interior, repoints mentioned in lines 3, 4 cored, established or re-established ration for Land Surveyors or, by a
እአአውድአክክክልአክአክአክአክ B. Continued: between fd			
C. Continued: M-9 Fd. Wexford Co. mon. w/loc tag.	added ced. post	Drove 5/8" rerod w/loc tag.	2 w/RLS cap & ced. post
*16" W. Birch S *10" Maple S *10" Cedar cluster N Creek (course Wly.) N	60°E 30.30 32°E 12.61 16'±	10" Maple 5" Maple 6" Maple Fd. 1/2" pipe	S40°E 33.2 N11°18'E 13.79'
M-7 Fd. Fargo 3/4" pipe ( U.S. stream tie South nearest 1/4 chain.)	as placed by RLS, J. witnessed in 1968. as established by RL . A fence corner (f 1913) & one Fargo Wi 264'± very good & U	Wilcox in 1974 at pos Fargo had good origin S, J. Wilcox midway & n S & W) is 3'±W ∮ 3'± 5 t; a W.Pine stump 36" .S. stream tie E 235'	ition of fd. Fargo (1913) al Govt. corner here. on line between the SW & i. N15°W, 122.8'. Cor. fits measure (U.S. = 250' to
M-9 Fd. & accepted Wexfor per old survey of Sec 2 Established NW cor. of C. Description of monument fo	NE1/4-NE1/4 of Sec. r corner and accessories estab	24 per std BLM instruc dished to perpetuate locating the	tions or midway and on line position of the corner:
ced. post w/loc tag *16" Tamarack N30°E 28 *16" Tamarack N73°W 19 *14" Tamarack S44°E 20 *24" remains of S50°E 34 W.Pine stp (w/scribing)	ced. post .32 *5" W. Pine .13 *13" Maple cl .43 8" W. Birch .4 * Old Wits	w/loc tag 519°W 4.00 ump N84°E 66.23 8" N68°W 35.45 7" 9"	Fargo pipe replaced w/Wex- ford Co. mon. & added ced. post w/loc tag. Maple S05°E 10.8 Maple S73°W 39.1 Cedar N82°W 26.1 eek (2' wide) S. 257'±
* = 1968 Wit trees & stum (J.L.W.) SIGNED BY J. SURVEYOR'S MICHIGAN RE		DATE_ <b>5-</b> //-	eek (2' wide) S. 257'± C. Wly  OF MICHOEN  F. ROSER  (SIAL) LAND  SURVEYOR  No.
SURVEYOR'S MICHIGAN RE	GISTRATION NO1	2028	F. ROSER *(SAL) LAND *SURVEYOR
FOR STATE AND UNITED S	TATES AGENCIES:		SURVEYOR No. 12028 No. 12028 LAND SURVEYOR
SIGNED BY	CHIEF OF KURVEY RADTY	DATE.	STATED LAND SOLITA
APPROVED AND SIGNED BY	MICHIGAN REGISTERED L	DATE	
SURVEYOR'S MICHIGAN RE		Ë	iberty Township EXFORD COUNTY