LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Corner Code #

Located In

For Corners In:

Wexford (County)

1. Public Land Survey	T 24N R 9W K1	
Property Controlling in Section	T R	
Miscellaneous Property in Section	S T R S T R S T R R S T R R R S T R R R R	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	——— АВС D E F G H I J <u>K</u> L M
5. Private Claims:		2 6 5 4 3 2 1
requirements of PA 74, Mi- and 2 above were in confo- the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established	field survey on Aug. 15, 2006 do hereby state chigan PA of 1970, the corner points mentioned ormance with regulations and rules therefore as revey instructions of the United States Departmenagement or by a decree of a Court of Law and/lines 3, 4 and 5 above were in conformance with Land Surveyors or by a Decree of a Court, monumented, recovered, found as expressed by a Corners, all in the same town and rangertificate.	hat under in lines 1
		12 31 32 33 34 35 35
		13
A. Description of origina	al monument and accessories and/or subsec	
3) Hemlock 10" S72 4) Cedar 12" S10°E - 1912 – CSR – L. 1, - Pine Root Stake – (to 'K12'); E. 2640' - 1914 – Schaaf Indestuck - 1957 – WCRC Rd.	/ 15 L. = 29 L. . T24N, R9W – V. W. Caukin 2°W 29 L. = 20 L. , p. 495 – G. T. Co. Rec. – E. P. Waterman - 5) Hem. Stp. 24" N62½°W 45.6'; N. 2631' (to 'L13'). ex – Corner located and marked stakes Plans and Wit. Sheet – Steel fence post; 0°E 64.30'; 7) 10" W. Pine N45°W 48.02';	- 1980 – LCRC – L. 3, p. 237 & Rec. Sur. – L. 1, p. 849 – Wex. Co. Rec. – J. L. Wilcox – Fd. steel fence post 3' Deep 0.5' N. of centerline, 8' W. of centerline N., raised post w/ Wexford Co. Mon; 6) N60°E 64.43' USGS BM; 8) S43°W 37.11' - 6" Maple; 7) N27°W 48.49' - 14" W. Pine; 9) S10°W 31.17' - 4" Basswood; 10) S10°E 3.05' - ½" rerod. - 1989 – LCRC – L. 3, p. 216 – G. T. Co. Record – R. F. Mitchell – Fd. Wex. Co. Monument. Same witnesses as Wilcox
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:		
poor condition ove grid distance North N & S area from 0. ½" x 18" rebar note GLO Wits. Fd. WO	er "U" x 2.7' long fence post iron in centerline in 2627.12' to 'K12' and East 2639.47' to 'L1' .5' N. to 5.5' S. of Co. Mon. to a depth of 4'± ed by Wilcox was removed and searched ur	c. 1 & 2, T24N, R9W – Fd. 4" x 1.6' long Alum. Wexford Co. Mon. in of E-W Bit. Rd. Centerline of gravel road North is 7.5'± E. Measured '. Based on Waterman's survey notes excavated 2'± E-W by 6'± looking for evidence of Pine root stake but found nothing. A bent der during the excavation. Waterman's Witness to NW is gone. No w/ Alum. Mon – 2 of them dead or dying (#9 & 8). Wexford Co. dence of the position of the original corner.
C. Description of monur	ment for corner and accessories established	to perpetuate locating the position of the corner:
Mon. Box. South 33.01' to se N30°W 48.41' to s N42°W 62.27' to s N54°E 64.45' to fd S37°W 69.22' to s	d Co. Mon. and fence post iron w/ Grand Tract 2" Alum. Cap on 5/8" x 34" rebar on line with the Nail & Tag (N & T) in SW side 30" W. Pinset N & T in NE side 20" R. Pine I. USGS BM and add Orange Carsonite Poset N & T in NW side 8" Cedar scribed 'XBT' spike set in place of bent 1/2" rebar (#10)	CRAIG W. McVEAN PROFESSIONAL SURVEYOR
Signed by:	mgW. Me Ven	Date: 3/15/2007 No. 39088
Surveyor's Michigan	License No.: 39088	A PORESSIONAL