LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Corner Code #

For Corners in:

Wexford		Located In	Corner Co	de#		
(County)						
1. Public Land Survey	T T	_24N R 9W R	<u>l-1</u>			
Property Controlling in Section	S T	R				
3. Miscellaneous	S I	R				
Property in Section	S T S T	R			Register of Deeds	Stamp & File Number
4. Lot No:	Recorded Pla	at:			ABCDEFO	S H _ J K L M
5. Private Claims:					2 6 5 4	3 - 1 - 1 -
I, <u>Craig W. McVean</u> , in a requirements of PA 74, Mi and 2 above were in conforthe current manual of sur Interior, Bureau of Land Macorner points mentioned in of the Michigan Board o established, re-established NOTE: Not more than be recorded on this ce	chigan PA of 195 crmance with regirvey instructions anagement or by lines 3, 4 and 5 if Land Surveyor i, monumented, re 2 corners, all	70, the corner points ulations and rules th of the United State a decree of a Court above were in confors or by a Decree ecovered, found as e	mentioned in erefore as request Department of Law and/or formance with the of a Court compressed below	lines 1 uired in of the that the ne rules of Law; w:	4 7 8 9 - 5 5 6 -18 -17 -16 - 7 8 -19 -20 -21 9 10 -30 -29 -28 -11	
					12 31 32 33	35-36-
A. Description of original monument and accessories and/or subsequent restoration:						
1 - 1838 - GLO - Set Post - J. Brink 1) Pitch Pine 10" N58½"W 102 L. 2) Pitch pine 10" N23½"E 70 L. 2. 2) Pitch pine 10" N23½"E 70 L. 2. 2) Pitch pine 10" N23½"E 70 L. 3) Y. Pine 18" S21"E 147 L. 4) Y. Pine 18" S21"E 147 L. 4) Y. Pine 12" S47"W 121 L. 1913 - Fargo Eng Fd. Stps. of 3 U.S. Wits. Two in 24-9 and One in 25-9. Set iron and crockery Mon. 5) S. Pine 5" S26½"E 138 ½; 6) Pine 5tp. 10" S49½"W 126 ½. 1914 - M. Schaaf Index - Corner located and marked stake stuck - iron set 1957 - WCRC Rd. Plan and Wit. Sheet - Steel fence post; 7) 12" J. Pine N15"E 75.75; 8) 4" J. Pine S30"W 43.30"; 9) 10" J. Pine S45"E 78.58"; 10) 14" J. Pine S30"W 43.30"; 9) 10" J. Pine S45"E 78.58"; 10) 14" J. Pine S45"E 95.65' B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: -1 - Standard corner common to Sec. 34 & 35, T25N, R9W and Sec. 2 & 3, T24N, R9W - Fd. 2" x 0.9" long axel casing w/ hub w/ poured conc. base - Down 1' - in Bit. Rd. Common Schaaf monument in area. GLO witnesses are gone. Fits remains of fallen Fargo Wit. to SE (#5) - found scribed "S2" and also stp. hole for the SW Witness (#6). Schaaf Mon. is 5.5' S. of centerline E-W Bit. Rd. and 8"± W. of centerline of Firelane N. Schaaf Mon. accepted as a careful and faithful perpetuation of the position of the original corner. - Reference Pt Fd. 5/8" iron rod N30"28W 6.83' from "I-1". 5/8" rod fits one 1957 without regard to the original perpetuation by Fargo and Schaaf. The 5/8" rod has been used for the plat of "Chippewa Creeksites" and Rec. Surveys by Wilcox. 5/8" iron rod not utilized as 'I-1' in this survey.						
·					locating the position of the	
South 33 01' to se	at 2" Alum. Cap et ½" x 18" reba et Nail & Tag in d. nail in SW sid fd. nail in S. sid	on 5/8" x 34" iron ar in centerline rem NE side P.P. de 10" R. Pine le 16" W. Oak	rebar on line	with Blue Ca	on 2 ¼" x 30" galv. iron pi rsonite Post w/ loc. tag. et scribed face "S2" alongs	CRAIG W.
Signed by: Surveyor's Michigan	in W.	millam	_	Date:	3/15/2007	PROFESSIONAL SURVEYOR No. 39088
Surveyor's Michigan	License No.:	39088				39088
,	V					POFESSIONAL
						OCIONAL CUENTIVORS IANI 22 4074