


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

WEXFORD COUNTY
T 24 N R 10 W

DESCRIPTION OF CORNER Sec. corner common to Sections 7-8-17-18
CORNER MONUMENT Set Std. Dept Mon & Cedar Guard post
DATE MONUMENT PLACED AND WITNESSED 7-6-70
WITNESSES TO CORNER..... _____



16" Oak S 77 W 13.5'
14" Oak N 02 W 23.8'
AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while make a retracement survey in this area. Found Fargo bottom of hole butter dish and remains of both Fargo witnesses. Fargo's 3/4" pipe had been pulled and was lying under a blown down Hemlock. Accepted Fargo Engineering corner, 1913, as proper SE corner of Section 7.

SURVEYOR'S SEAL

SIGNED

Carl F. Roser
REGISTERED LAND SURVEYOR

DATE

7-17-70

DISTRIBUTION:

12028

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68