STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		_	WEXFORD		COUNTY	
		T		N	R _	10 W
DESCRIPTION OF CORNER 1/4 corner	common to Sections 5	<u>.</u>	88	 -		
CORNER MONUMENTFound 4" ro	ound concrete monumen	ıt				
DATE MONUMENT PLACED AND WITNESSED	7-10-70	···•				
WITNESSES TO CORNER						
N	10" Maple	<u>-</u>	N.	78 E		25.9'
8	18" Beech		N.	15 W		57.7!
CIRCLE CORNER REGISTERED				·		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a retracement survey in this area. The concrete monument was set by Wilcox & Erickson, RLS, Manton, at the position of a found Fargo Engineering corner. The corner falls in E-W fence remains.

SURVEYOR'S SEAL

STONED

7-17-70

DISTRIBUTION:

REGISTERED LAND SURVEYOR 12028

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing