

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 24 N. R. 10 W.


Wexford COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 27 - 28 - 33 - 34

CORNER MONUMENT Set 1 1/4" pipe over existing corner

DATE MONUMENT PLACED AND WITNESSED April 17, 1962

WITNESSES TO CORNER..... Set 1 1/4" pipe over existing corner.



CIRCLE CORNER REGISTERED

Power Pole N 37 N - 71.0'

SW Cor Foundation N 47 E - 183.6'

AND Rd. Sign Post S 62 E - 41.2'

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Found iron and broken crockery at corner in intersection of N - S - E county roads. Previously located and used by County Road Commission. Set 1 1/4" x 20" pipe over existing corner to surface of road.

SURVEYOR'S SEAL

SIGNED *Henry J. Oetting* DATE April 24, 1962
REGISTERED LAND SURVEYOR