LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 24 N., R. 10 W.	D-11; E-10; E-11
2. PROPERTY CONTROLLING IN SECTION 29	,T. 24 N., R. 10 W.	7; 16
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Sept. 27, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued)

7			16		
Set 5/8"X40" re-rod w/plastic cap.&Ced.Post w/Loc.Tag.			Fd. 1" pipe,Set Ced.Post w/Loc. Tag.		
11" Cedar	N42°E	47.5	24" W.Pine stp.	N16°E	46.6
10" Cedar	S78°E	22.0	7" Maple	N22°W	94.3
5" Maple	S78°W	8.5	6" Maple	N48°W	109.3
N-S Fn. remains	Due E.	20'±	Fd.Conc.Mon.	Due S.	1.2'
E-W fn. remains	Due S.	176'±			
Apple Creek	Due W.	52'±			
Apple Creek	Due S.	86'±			

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-11 Fd. Conc. Mon. as recovered & accepted by Dept. (1962).

E-10 Fd. Dept. Mon.(1962) as established S.P. Corner falls somewhere in middle of fairly open water hole, 350'± dia.

E-11 Fd. Dept.Mon(1962) which perpetuates Schaaf Mon.(1938) who had Govt. evidence.

7 Established 1/8 Cor. per standard B.L.M. instructions.

16 Fd. 1" pipe Dept. Survey (1962) as established S.P.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-11			E-10			E-11		
Fd. Conc. Mon.,			Fd. Dept. Mon,Set Ced.Post			Fd. Dept. Mon. & Ced.Post		
Set Ced.Post w/Loc.Tag.			7" Cedar	S03°W	142.5	20" W.Pine	S76°E	84.4'
10" R.Pine	N68°W	132.7	6" W.Pine	Due N	250.2	26" W.Pine	S02°E	81.4'
5" Maple in Clump						21" R.Pine	N08°E	137.3'
	S54°E	34.8				N-S Trail Rd.	Due W.	230'±
8" Maple in Clump						E-W Trail Rd.	Due S.	30'±
	N41°E	69.0						

SIGNED BY Carl F. Roser 10-2-78 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

GREENWOOD TOWNSHIP
WEXFORD COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET