LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 24 N., R. 10 W.	B-11; B-12; B-13
2. PROPERTY CONTROLLING IN SECTION 31	,T. 24 N., R. 10 W.	3
3. MISCELLANEOUS PROPERTY IN SECTION _____	,T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 29, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. [illegible]

C. (continued)

3

Found 1"x36" pipe & cedar post

6" Maple	S57°E	34.4
12" Maple	Due N	55.6

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

B-11 Recovered and rewitnessed previous Department corner of record.

B-12 Established center of Section 31 at intersection of one-quarter lines.

B-13 Found 1¼" pipe believed to be at same position as Devoe corner recovered by A.J. Teed in 1886.

3 Recovered previous Department corner of record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-11

Found DNR mon. & cedar post

7" R. Pine	S48°E	41.7
5" Maple	N86°E	41.9
9" Maple	N24°W	28.3
5" R. Pine	N07°W	48.2

B-12

Set 1¼"x36" pipe & post w/loc. tag

9" Maple	N42°W	39.5
11" Maple (tan)	S70°W	75.6
5" Hemlock	S20°E	77.5
Fence corner E-W-S		79.9'
	N84°E	~~79.0~~
Fd. 1¼" pipe	N85°W	39.7

B-13

Found 1¼" pipe; add 7/8"x18" iron rod

28" Maple	S69°E	96.05
12" Apple	N23°W	91.15
Tel. Pole	N22°E	30.92
Fence North	Due E	4.0
loc.tag on corner fence post		
	N11°E	30.2
Center E-W gravel rd.	Due S	4.0

SIGNED BY Carl F. Roser 9-4-75 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

GREENWOOD TOWNSHIP
WEXFORD COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET