1.9, P. 57 1/16/2020

## **Land Corner Recordation Certificate**

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Craig vv. Micvean								Field Survey Date: July 7, 2019							
For corner(s) in:		Wexford				County	_								
Original P	ublic L	and Su	rvey	Corner	•		Corner Code							,	
S	17 &	20	T	24N	R	10W	D7								
s			_ T		R			-	ΑВ	CDI	E F (	3 H I	J	K L I	M,
s			_ T		R			- 1							,
S			T		R			2	6	<b>⊹5</b>	4	3	2	1	2
Property C	Control	llina Co	rner				Corner Code	3 4	<del>-</del>			- 10	- 1.1	12	3
S		9 00	т.		R		0011101 0040	•				- 10	111	12.	1
s		MARIPHANIP	— <u>т</u>		- `` - R		***************************************	- 5	4 5		10	4		40	5
s			T		R			- 6	- 18 -	+ 17 -	16	- 15	14	13 -	
s			_ T		R			7							7
Property Corner						Corner Code	- 8 9	19	20	21	22	23	24	8	
S	2011161		т		R		Comer Code							0.5	
s			— <u>;</u>		- '` - R			_10	30	29	28	27	26	25	10
s			— <u>;</u> Т		- · · · · · · · · · · · · · · · · · · ·			- 11			<del></del>			†	- 11
s		***************************************	T	***************************************	R		<del></del>	- 12		32	- 33 -	- 34	35	36	1
Protracted Public Land Survey Corner						Corner Code	<sup>-</sup> 13	A B	CDI	= F (	G H	ΙJΙ	K L I	<b>⊿13</b> М	
S			Т		R										
s			_ T		R			_							
s			_ T		R			_							
s			T		R										

## Part A: Corner History

- D7 1/4 Corner common to Section 17 & 20, T24N, R10W
  - 1852 GLO L. S. Scranton Set Elm post
  - 1) Maple 12" N9°E 16 L.; 2) Hemlock S5°W 36 L.
  - 1913 Fargo Eng. No. US evidence Set 1"Iron pipe and crockery monument. 3) WPS 22" S70½°E 31; 4) WPS 28" N51½E 40

  - 1937 M. Schaaf (PS # 3104) on random S87°30'E 34.57 intersect ¼ Cor. 4.56 South of post. Found SW witness
  - tree site. 22" W. P. Stump N89½°E 6.78 chs. Took NBT's 5) Wh. P. Stump 23" S51°E 49\*; 6) Wh. P. Stump 27" N13°W 66. \*This is a Con. Power Cor. witness scribed NBT which cor. is 21 lks. S and 8 lks. East of true corner.
  - 1962 DNR Field Notes Chaining E. from 0.027 N. of Cor. 17-18-19-20. 29.90 offset 1' N. 39.94 Int. 0.04 N. of 11/4" pipe by Schaaf. 40.025 int 0.25 North of CP 1/4 corner.
  - 1962 K. J. Ostling LCRC L. 3, p. 40 (1977) Fd. 1" iron pipe in place as established by Fargo Engineering for Consumers Power Co. in 1913. Corner was established by Fargo by proportionate measurement for lack of U.S. evidence. Both Fargo witnesses in place with marks plain. Set 1" pipe with 4" Brass Cap.

7) 12" R. Pine N77°W 103.2'; 8) 7" Maple S6°E 29.2'

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

D7 – ¼ Corner common to Section 17 & 20, T24N, R10W – Found 4" Dept. of Conservation Brass Cap on 1" iron pipe per Ostling at the Fargo position. Also found the remains of both of Schaaf's BT's which cross at a position N25°W 15.6'± of the DOC monument. No evidence of a monument or depression at the Schaaf position. No evidence of GLO BTs. Dug Schaaf's location but found no other evidence. It appears that Ostling removed the Schaaf pipe. Also searched for 22" White Pine line tree [6.78 W. Pine 22 – GLO] 448' to the east but could find no evidence of a large White Pine stump within any reasonable distance. Have always felt that Schaaf's calls to sites can be quite questionable. Schaaf makes the same questionable calls ½ mile East to a position for 'E7' that was rejected since it is completely out of position to the original government corners at 'E6' and 'E8'. The Fargo position at 'D7' fits very closely to original GLO distances and bearing for the line from corners 'C7' to 'G7'. Thus accepted the DOC monument as a careful and faithful reestablishment of the position of the original corner. Condition of witnesses as follows: #1 & 2 are gone; #3 - 21' to CL. remains; #4) 27.6' to centerline stp.; #5 & 6 – Not applicable to this position; #7 – Fallen over; #8 – Stump remains.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

<u>D7</u> - ¼ Corner common to Section 17 & 20, T24N, R10W – 4" DOC Brass Cap on 1" iron pipe – Up 1'. Set Blue Composite Post 1' South N29°W 13.84' to set N & T in E. side 5" Red Maple scribed 'XBT' N53°E 21.40' to set N & T in SE side 8" Red Maple scribed 'XBT' S82°E 22.51' to set N & T in N. side 5" White Pine scribed 'XBT' S5°W 26.28' to set N & T in W. side 6" Sugar Maple scribed 'XBT'



Craig W. McVean

Date

Professional Surveyor's License No.:

39088

Prepared By: Craig W. McVean

Michigan Dept. of Natural Resources

8015 Mackinaw Trail Cadillac, Michigan 49601