

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


WEXFORD COUNTY
T 24 N R 11 W

DESCRIPTION OF CORNER 1/4 corner common to Sections 1 & 12

CORNER MONUMENT Found 3/4" pipe in B. Top County Road

DATE MONUMENT PLACED AND WITNESSED 7-8-70

WITNESSES TO CORNER..... Ctr. E-W B. Top Rd Due N 6.5'



10" W. Pine N 30 W 107.2'

20" W. Pine N 51 E 103.7'

AND

Set Cedar Guard Post with Location Tag Due N 33'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a retracement survey in this area. The corner fits Wexford County Road Commission Witnesses.

SURVEYOR'S SEAL

SIGNED

Carl F. Roer

DATE 7-17-70

DISTRIBUTION:

REGISTERED LAND SURVEYOR 12028

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68