LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 24 N., R. 12 W.	A-1; B-1; C-1
2. PROPERTY CONTROLLING IN SECTION 6	,T. 24 N., R. 12 W.	1
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 22, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. ~~Description of original monument and accessories, if of subsequent restoration~~

C. (CONTINUED)

1

Fd. well pt. 15" deep & raised w/1"x12" pipe

38" Maple	N38°W	86.03
25" Maple	N01°W	45.72
9" Apple	S26°E	74.16

Set ced.post w/loc. tag Due S 33'
in line with fence to South
Fence to N Due W 2'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-1—— Fd. boat spk. in monument box that fits Walter Johnson survey of Sec. 6, dated 1916. Corner is in center E-W blacktop road with gravel road N and sand road S.

B-1—— Fd. ½" rerod in monument box in center of E-W blacktop road that fits Walter Johnson survey of Sec. 6 in 1916.

C-1—— Fd. ½" rerod in monument box in center of E-W blacktop road & in line with fences to N & S. Corner fits survey of Sec. 6 by Walter Johnson in 1916.

1—— Recovered well point in E-W blacktop road per Walter Johnson survey of Sec. 6 in 1916. IMPORTANT REFERENCE: Also read item "B" Sec. 6, Corner Code 8 (W 1/16 on E-W ¼ line). 1/16 Cor. Position, S.P. to U.S., would be 11.20' - West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-1

Fd. boat spk. in mon. box

12" Maple	S65°E	149.20
36" Maple	N65°E	115.30
9" S.Pine	N59°W	76.38

Set cedar post w/loc. tag S45°E 47'

B-1

Fd. ½" rerod in monument box

10" Maple	N03°W	69.28
25" Maple	S72°E	92.90
6" R. Pine	S23°W	62.04

Set ced.post w/loc. tag Due S 33'

Fence South	Due E	1'
Fence North	Due W	6'

C-1

Fd. ½" rerod in monument box

8" Apple	N02°E	71.69
13" Maple	S38°E	48.85
15" Maple	S54°W	47.75

Cedar Post w/loc. tag Due S 33'

SIGNED BY Carl F. Roser 4-28-77 DATE

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

WEXFORD TOWNSHIP
WEXFORD COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET