## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	h son
1. PUBLIC LAND SURVEY 16	_ T/	6 F	The Control of the Co
2. PROPERTY CONTROLL-	,T S., R E.		Montage Seits
3. MISCELLANEOUS PROPERTY IN SECTION			The Discount P. S.
4. LOT NO , RECO	RDED PLAT	·	P
5. PRIVATE CLAIMS	<del></del>		REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1972, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  RECOVERED /'Z" IRON PIRE IN ROEPKE RD. FROM WITNESS  INFORMATION FURNISHED BY M.D.S.H.			
C. Description of a company (		essbliched to servetuate for	nting the position of the corner.
12" IRON PRE N57W 557W		y	ating the position of the corner:
SIGNED BY			
SURVEYOR'S MICHIGAN REG			(SEAL)
FOR STATE AND UNITED ST			
SIGNED BY	CHIEF OF SURVEY PARTY		
APPROVED AND SIGNED BY	MICHIGAN REGISTERED CAN	DATE	(SEAL)