SURVEY & REMONUMENTATION

•

MAY - 1 1995

	COMMIS	1995 SSION EIII.		CORDATION CER	
For corners in	Car (Spr x b x p. 4 L 1 Ca	Full Fill	ig Requirement	of Act 74, Mich.	E S V
Washtenaw	untyj	Located I	n: Ce	orner Code ##	O TREE
1. Public Land	d Survey	. T.1S	R_4E: R	<u>I-11</u>	
			R		26 M '94 RAINES K/REGISTER
		Т	R		P. A. H. A. L. H. H. H. A. L. H. H. A. L. H.
2. Property Co		§ <u>T</u>			# 4 4 A 50 A
in Section 3. Miscellane		S T S T			LIBER 1 PAGE 12U 4
Property in		5 T			Register of Deeds Stamp & File Number
4. Lot No	, Reco	orded Plat			- Copy -
5. Private Clai	ms				
•	:				2 6 5 4 3 2 2 1
				-	4 7 8 9 9
R.Timothy	rietsema in	a field survey on	April 20	, 19 <u>94</u>	
do hereby certify	that under require	ments of P.A. 74, M	ichigan P.A. of 1970, t	he corner points men	ntioned -
in lines 1 and 2 a	above were in cor	nformance with reg	julations and rules t	herefore as required the Interior, Bureau o	in the
Management or b	y a decree of a Co	urt of Law and/or th	at the corner points r	nentioned in lines 3,	4 and 5 8 19 20 21 23 23
above were in cor	nformance with the	e rules of the Michi	gan Board of Land Se	urveyors or by a Decr	ree of a
expressed below	stablished, re-es :	tablished, monum	ented, re-monumen	ited, recovered, fou	und as
•		are all in the ear	ne town and range	e, may be recorded	23 20 21 20 21
	certificate.	as, an in the san	ie town and range	, may be recorded	12 31 32 33 34 35
					13 1 32 33 34 35 36
			sories and/or sub	sequent restoratio	
<u>DATE</u> 1819	SURVEYOR GLO (Wampler)	LS# LCRO	SURVEY Fld. Notes	MONUMENT DE Set Original Corner	
	Set post Corner of		rid. Notes	set Ongmai Comer	1) 6" W. Oak N47E 62 links(40.92")
	Sec. 26, 27, 34 & 3	15			2) 10" W. Oak N20W 146 links(96.36')
	300. 20, 27, 34 60 3				
11/19/1934	W. J. Armstrong		Resurvey	40" Elm is the Come	er No witnesses given.
	of corner evider C found a 1" iron pipe Fnd. 1" of remain Tree in	nce found and/or eusing these witnesses: IP at approx. center ins of Large Dead old fence line to S., E-W fence line.		n restoring or rees \$30W 10.6' \$60W 6.7' \$80W 12.8'	tablishing corner:
					ocating the position of the corner:
April 20 1994	R. T. Tietsema	20712	Remon.	Fnd. 1" Iron Pipe Added a Wash, Co.	9) 14" Ash S15W 10.69' to nail & R.T. 10) 12" Cherry S60E 6.39' to nail & R.T.
				Remon. Cap.	11) 12" Thornapple N80W 12.93' to nail & R.T.
					12) 12" Box Elder S85E 19.55'
It is our opinion that th	tis corner represents t	he original corner and	is accepted as the <u>best a</u>	vailab <u>le evidence</u> of the	e position of the original corner.
· '/		2			
Signed by	Saust		(face)	Date M	ay 6 1994
Surveyor's Michig	an License No.	20712			FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19

DATE	ROM A. ON FRONT: SURVEYOR	LS#	LCRC	SURVEY	MONUMENT DESC.	WITNESSES		
Unknown	Atwell-Hicks			Fld. Notes	48" Elm is the Corner At Intersection N-S and E-W Fence Line.	3) 36" Butternut 4) 8" Tree 5) 26" Oak 6) 14" Oak 7) 2" Cherry	WEST NORTH EAST EAST WEST	
						8) 16" Tree	NORTH	
8/25/1976	N. N. Fahrner JOB NO: 13907	17620	L4P244	Boundary	Fnd Dead Tree	9) 8" Ash 10) 8" Cherry 11) 8" T. Apple	\$30W \$60W N80W	10.6' 6.7' 12.8'
12/27/1977	N. N. Fahrner JOB NO: 15160	17620		Boundary	Fnd Dead Tree	•	\$30W \$60W N80W	10.6' 6.7' 12.8'
8/2/78	N. N. Fahrner JOB NO: 15948	17620		Boundary	Fnd Dead Tree	,	S30W S60W N80W	10.6° 6.7° 12.8°

APPROVED

DATE <u>5/3/94</u>

CO. REP. <u>K</u>