## SURVEY & REMONUMENTATION

ì

}

	SMAY - 119	95 LAN	O CORNER REC	CORDATION CERTIFI	CATE LIBER 1 PAGE 12				
For corners in Washtenaw	COMMIS		g Requirement	of Act 74, Mich. P.A.	1970 COUNTY ASHT				
(Co	ounty)	Loodiod III		511161 Gode	REC FENA POCK				
1. Public Lan	d Survey	T 1S F	R R	I-13	II 26 AN 94				
Property C     in Section     Miscellane	S	T F S T F S T F	R R						
Property in		S F			Register of Deeds Stamp & File Number				
		rded Plat			A B C D E F G H 1 J K L				
I, R.Timothy Tietsema , in a field survey on May 18 , 19 94 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, re-monumented, recovered, found as expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be recorded									
on this	s certificate.				12 31 32 33 34 35 36				
A. Description	n of original mon	ument and access	sories and/or sub	esequent restoration:	13				
DATE 1819	SURVEYOR GLO (Wampler)	LS# LCRC	SURVEY Fld, Notes	MONUMENT DESC. Set Original Corner Set post for the cor. of Sections 34 & 35. 4.60 between Sections 2 & 3, T	WITNESSES  1) 20" W. Oak EAST 576 links(380.16') 2) 24" W. Oak S10W 275 links(181.50') chains (303.60') East of Corner 2S, R4E, Lima Twp.				
Sept 1936	W. J. Armstrong	W.C.R.C.	Resurvey	Fnd old rotted end post in the muck. Set I 1/2" x 36 Iron pipe, stones and brick					
CONTINUED ON BACK B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:									
in May of 1994, LSC	C found a 1 1/2" Iron p	pipe using these witness	ses:						
	w/stone of Maple	/2" Iron Pipe & brick @ SW cor. e Hardwood swamp line int. E-W & N.	7) 12" Maple 9) 6" Willow 10) 5" Willow 11) SW Cor. Fnc.	N05E 45.9' S75W 9.4' WEST 50.3' Post N10E 1.1'					
C. Description	of monument fo	r corner and acce	essories establish	ed to perpetuate locati	ng the position of the corner:				
May 18 1994	R. T. Tietsema	20712	Remon.	Fnd. 1 1/2" Iron Pipe w/stone & brick @ SW cor of Maple Hardwood swam @ fence line int. E-W & N.	7) 15" Maple NORTH 45.96' to nail & R.T. 9) 16" Tw. Willow S75W 8.67' to nail & R.T. 10) 12" Tw. Willow WEST 56.67' to nail & R.T.				
It is our opinion that t	this corner represents t	he original corner and i	s accepted as a careful	and faithful <u>perpetuation</u> of the	ne position of the original corner.				
. (	-	1			•				
Signed by	Jamos	1 Soul	Jane L	Date Octobe	т-3, 1994				
Surveyor's Mich	igan License No.				K APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971				

CONTINUED I	FROM A. ON FRONT: SURVEYOR	LS# LCRC SURV	EY MONUMENT DESC.	WITNESSES
1967 ?		ions in Witness Book wwitness numbers 3-6 (four Elm t	Fnd. at E-W Fence line & fence line N'ly.	7) 6" Maple N05E 46.4" 8) 4" Triple Elm N60E 48.8"
8/25/1976	N. N. Fahrner JOB NO: 13907	17620 L4P245	Fnd. Iron Pipe	7) 12" Maple NOSE 45.9" 9) 6" Willow S75W 9.4" 10) 5" Willow WEST 50.3" 11) SW Cor. Fnc. Post N10E 1.1"
8/2/1978	N. N. Fahrner JOB NO: 15948	17620	Fnd. 1 1/2" Iron Pipe	7) 12" Maple NOSE 45.9' 9) 6" Willow S75W 9.4' 10) 5" Willow WEST 50.3' 11) SW Cor. Fnc. Post N10E 1.1'
12/21/1989	Lawrence O'Donell JOB NO: 15948	28419	Fnd. 1 1/2" Iron Pipe	7) 12" Maple NOSE 45.9' 9) 6" Willow S75W 9.4' 10) 5" Willow WEST 50.3' 11) SW Cor. Fnc. Post N10E 1.1'

APPROVED

DATE 6//3/94

CO. REP. 4