## SURVEY & REMONUMENTATION

MAY - 1 1995

For corners in



WASHTENAW COUNTY. MI

RECORLED

JAN 10 9 50 AM 95

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Washtenaw (County)	Located In:	Corner Code ≠	county Glerk/Register —COPY—
Public Land Survey     .	T <u>1S</u> R <b>7E</b> T R T R T R	L-9	LIBER 1 PAGE 330 RM
<ol><li>Property Controlling in Section</li></ol>	S T R S T R		-copy-
Miscellaneous     Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No , R 5. Private Claims	Recorded Plat		A B C D E F G H J K L N
do hereby certify that under rec in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance wit	d in a field survey on	of 1970, the corner points mentioned d rules therefore as required in the ment of the Interior, Bureau of Land r points mentioned in lines 3, 4 and 6 f Land Surveyors or by a Decree of 8	1 6 18 17 16 15 14 13 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11 2 31 32 32 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

(Irvin E. Chope #6504 1969) Homestead Acres Subdivision Liber 19 of Plats, Page 43 & 44, Washtenaw County Records Concrete Monument Centerline Napier Road N88°06'18"E 940.60

(Brender-Hamill 1974) McClelland Subdivision Liber 20 of Plats, Page 9, Washtenaw County Records Centerline Napier Road N88°00'42"E 940.60

(Ambit Land Surveyors 1988) Concrete Monument P.K. Nail in E. Face 10" Fence Post N10°W 1.57 Steel Bar - #17022 EAST 7.10 Nail in N. Face of Utility Pole EAST 27.04
Nail in E. Face of Utility
Pole S25°E 58.76

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Concrete Monument in Range of Fence line to the North.

APPROVED

DATE CO. REP

Description of monument for corner and accessories established to perpetuate locating the position of the corner;

Concrete Monument 10" Fence Post NO5°W 1.53 to Nail W/W.C.R. Tag in E. Side Iron Pipe in centerline Napier Road EAST 940.51 3/8 Rod EAST 26.17 Power Pole S87°E 27.07 to Nail W/W.C.R. Tag Iron Rod (used by Boss

Engineering and others as 1/4 Corner) EAST 7.15
Steel Fence Post S75°E 7.02 Steel Pence Post S50°W 4.08

Power Pole S88°W 122.36 to Nail W/W.C.R. Tag in E. Side 6" Spruce S10°E 32.94 to Nail W/W.C.R. Tag 6" Spruce S30°W 37.32 to Nail W/W.C.R. Tag 12" Pine S65°E 42.22 to Nail W/W.C.R. Tag

٦.

D'conclude that after careful study of the record documentation and field observation, that this corner is accepted as the best available and the best available is accepted as the best available evidence of the position of the original corner. ু Date

la 1 Sutt Signed by Thomas L. Sutherland
Surveyor's Michigan License No. 1020

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

December 15, 1994