SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

NOV 02 1999

0. 000.0									
WASHTENAW	Located In:	Corner Code <i>≠</i>	≠	4	SECTIC	M			
. Public Land Survey	T <u>2S</u> R <u>3</u> TR_ TR_		 		 5017:		•		
Property Controlling in Section Miscellaneous Property in Sec.	T R S T R S T R S T R S T R	Peggy M.		Co. COR	02/25/ REM L-2	1999 @ P-169)2:59P		
I. Lot No, R	ecorded Plat			A B C	DEFG	. н і		K L	м
5. Private Claims			2	Į į			<u>_</u>	\prod	
			3					\Box	
			4	 		_10_	<u> </u>	4-4	2
I. JOHN JEKABSON .	in a field survey on	<u>1 October</u> ,	19 98				_1	9 -1	
o hereby certify that under req o lines 1 and 2 above were in	uirements of P.A. 74, Michig	an P.A. of 1970, the corner poi ons and rules therefore as ru	ntsmentioned 6	181	716	15	14-	┼╌┆	3—
current manual of survey instru	ictions of the United States	Department of the Interior, B	ureau of Land 7		-1-1-1			╁╌┤	
fanagement or by a decree of a bove were in conformance with	Court of Law and/or that the	e corner points mentioned in I	ines 3, 4 and 5	19-1-2	0	22	23	 2	4
bove were in conformance with Court of Law; established, re expressed below:	n (ne rules of the Michigan e e-established, monumente	d, re-monumented, recover	ed, lound as	-302	9 28	-27-	<u> </u>	╂╌┦	 5
NOTE: Not more than 4 co	orners, all in the same to	own and range, may be re	corded 11	┠━┼╍┼╍┤				╂┤	
on this certificate.			12	313	233	-34	35 	 3	6
A. Description of original r	nonument and accessori	es and/or subsequent res	toration:	1					_
824 G.L.O JOHN M. N			White Oak, 5" White Oak, 25"	\$ 56°E N 31°W	0,56Chs. 0,65Chs.				
1934,14 Aug. WASHTENAW C COMMISSION W.J. ARMSTRO		rood stake and stone. 0x42" Iron Pipe, stones and	Twin Yellow Oak, 6" Twin Yellow Oak, 6" Willow, 12" 18" East of North & South Fence	North North S 10°W	54.6 56.2 226.8		1 2 3		
SEE BACK OF THIS SHEET (NE FOR CONTINUATION OF SECT			1/2 Post Common to Sections 11 & 12	North	2673.0				
3. Description of corner e	vidence found and/or me	ethod applied in restoring	or reestablishing cor	ner:					
FOUND 11/3" IRON PIPE									

corners in

USING 8 WITNESSES FROM SECTION "A"



	orner and accessories established	N 05°W	19.70	4*	
SET 1/4" IRON PIPE WITH REMON	Mag & RT in W sd Tri 24" White Oak				
CAP IN THE FOUND 11/2" IRON PIPE TOP OF REMON CAP IS 6" ABOVE THE GROUND.	Mag & RT in S sd Utility Pole	East	58,90	6*	
	Mag & RT in E sd 12" Cherry	S 10°E	7.01	14	
	Mag & RT in N sd 8" Red Oak	S 80°W	11.96	11*	
	Nail in 4" Maple	S 85°E	11,25	13*	
	Center of 12" Red Oak Center of 22" Red Oak Center of 22" Red Oak Center of 12" Elm	North North North	48' 54' 56' 53'	9* 1* 2* 5*	
					Legend:
					Mag & RT = Magnetized Nail &
		South			Washtenaw Co. Remon. Tag * Indicates Previously Used

I conclude that after careful study of the record documentation and field observations, that this corner is a careful and faithful perpetuation of the position of the original corner.



Signed by _ Surveyor's Michigan License No. 19836

22 December, 1998 Date __

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963

APPROVED DATE 12-14 CO. REP.

1998 WASHTENAW COUNTY REMONUMENTATION PROGRAM
SYLVAN TOWNSHIP TOWN 2 SOUTH, RANGE 3 EAST
K-\$ (SECTION CORNER COMMON TO SECTIONS 11,12, 13, & 14)

Legend:
 Indicates Previously Used

Page: 2 of 2 02/25/1999 02:59P L-2 P-170