## SULVEY & REMONUMENTATION

ĨΥ	1AY - 1 199			ECORDATION				
, mar	V~8.65.81.00.00	Filing	g Requireme	ent of Act 74, N	lich. P.A. 19	70		est.
	OMMISS	ION					를1-13 <b>%</b>	WASHIE
For corne	ers in							SHT
Was	htenaw	_ Located in	a: - Lima Twp	Corner Code		Ĺ	29	
i	County				1	_0	5.2	Po My Condition May
1. Public Land	Survey	T 2 S	H 4 15	I-13		$\sigma_{\cdot}$	SE C	ရွိ ရွှင်း ရွှင်း
		Т			<u> </u>	K		
		Ţ					- E	<u> </u>
2. Property Co	ntrolling	T				,		
in Section	······································	S T	R			7 19	86 86 RI	m
3. Miscellaneo		ST	R			-CAN	1	
Property in	Sec.	S T	R		Hegis	ster of Deeds	Stamp and F	lle Number
		orded Plat						
5. Private Clair	ms		<del> </del>		<del></del>	A B C	DEFG	HIJK
						2 6	5 - 1 - 3 - 1 - 3	2
						3		
Michael S H	ahen in	a field survey on Tu	esday lannary	17 1003		\ \ \	8 9 10	( 0
		equirements of P.A. 7			corner points	5		
		ove were in conforma				6 - 18 -		5 — 14 — -
		al of survey instruction				7		<u> </u>
		agement, or by a dec				8 - 19 ;	20 21 2	2 - 23 -
		and 5 above were in by a Decree of a Cour				9		
		d, recovered, found a			ionou,	10 - 30 - 3	29 28 2	726
		ners, all in the same				11		
	ed on this ce		, to wit attait	ingo, may be		12 -31 :	$\frac{1}{32} + \frac{1}{33} + 3$	4
						13	<del></del>	<u> </u>
A. Description	of original mor	nument and accessor	es and/or sub	sequent restorati	ons:			
Monday, January 0	1,1816	B. Hough			G.L.O	Set pos		
Witnesses;								
		) W 275 LINKS (181.50°) ST 57 LINKS (37.62°)					-	
Thursday, August !		W. J. Armstrong	2444 W	CRC	Grid I	Book Fd. woo	id stake & bricks	with
•		, and the second				stones a	round It. Fd. stum	lo of
<b>38</b> (* .						witness	tree.	
Witnesses:	12" W. ASII N 3	6 E 44.1'						
	24" WALNUT S							
	5" ELM S 80 W 8							
	8" B. MCKORY 12" BASSWOOD							
	12.2' W. OF FEN							,
	8.0' N. OF FENC		12000 111	con a	1 7 70	T1 111		
Friday, December 1 Witnesses:	16, 1983	R. A. Campbell	13028 W	CRC	L7-P2	FG, 1" i	ron pipe & bricks.	
	26" W. ASH N 3:	5 E 44.2'						
	30* WALNUT S							
	24" DEAD BASS 12.3' W. OF FEN	WOOD N 10 W 24.0'						
	8.8 N. OF FENC							
	16" ASH S 78 W							
	17" ASH N 8 W : of corner evide	zr.v ence found and/or me	thod applied i	n restoring or ree	stablishing cor	ner:		
•			1.	. 5	<b>.</b>			
'd. 2" iron pipe with VCR cap.	i fed pijck. Sei							
•	of monumous 4	ar onther and access	oriae ostablici	had to nametusts	locating the s	asition of the	COURSE.	
•		or corner and access				ostinu oi iue i	JUHIOF.	
Tuesday, January 1	2, 1993	Orchard, Hiltz & 2 McCliment, Inc.	21584 OHM	4	W.C. Remon			
Witnesses:								
1	36"W ASH NO	8 E 44.40' TO PK NAIL W	ITH WCR TAG					
2	36" WALNUT S	11 W 12.90' TO PK NAIL	WITH WCR TA			•		
		60.50' TO PK NAIL WITH 40 E 15.08 TO PK NAIL W						
		40 E 13.08 10 PK NAIL WIT V 32.42' TO PK NAIL WIT		•				

We conclude that after careful study of the record documentation and field observations, that this corner is accepted as a careful and faithful perpetuation of the position of the original corner. Signed by Michael S. Hoben
Surveyor's Michigan License No. 35994
Orchard, Hiltz and McCliment, Inc. 34935 Schoolcraft Road Livonia, MI 481

<u>S</u>

**APPROVED** 

CO. REP.