MAY 0 9 1996

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

3. Miscellaneous

Property in Sec.

Washtenaw Located In: Corner Code ## (County)

M-9T \_ 2S R 5E 1. Public Land Survey \_ R \_\_ R T \_ R 2. Property Controlling Т S \_ T\_ \_ R . in Section

T

S

Register of Deeds Stamp & File Number

\_\_ , Recorded Plat \_ 4. Lot No. Private Claims \_\_\_

\_\_\_ R \_\_

Thomas L. Sutherland in a field survey on \_ October 10 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1815 Field Notes Unknown G.L.O.

6" Hickory S30°W 24 Links 12" W. Oak NO4°W 39 Links

Jan., 1951 W.C.R.C. or Grid Book 3/4" Iron Pipe M.S.H.D. R. Graf

NE Corner of Concrete Block Building N77°W 104.: 30" Oak N19°E 76.04 16" Oak S17°E 102.58 \*3)

10

184.1 to NW Cor. Sec. 30, T25, \*6)

(SEGTION A. CONTINUED ON REVERSE SIDE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Nail in Pavement between center turn lane and 2nd Northbound Lane on Maple and South of Dexter from remaining witnesses.

\*Old Witness Found

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I conclude that after careful study of the record documentation and field observations, that this corner is accepted as the best available evidence of the position of the original corner.

Set 1" Iron Pipe W/W.C.R.P. Cap in Monument Box NE Corner Block Building N79°W 104.09 \*3)

P.K. Nail A-9, T2S, R6E NORTH 184.42 \*6)

\*9) \*10) \*11) 12)

NORTH 184.42
Hydrant N35°E 64.92 to Top Nut
Telephone Pole S53°E 43.32 to Tag in S.W.
Power Pole WEST 43.00 to Tag in N. Side
8" Crabapple S40°W 93.66 to Tag in S.E. Si
30" Oak \$19°E 141.75 to Tag in S.W. Side
S.W. Corner Block Building N46°E 126.53

December 12. \_ Date \_ Thomas L Sutherland Surveyor's Michigan License No #24620

Liber 00001 Page 0558 Rm — Copy —

## (SECTION A. CONTINUED FROM FRONT)

Unknown	Grid Book W.G.R.G.	Unknown	7) 8) *9)	Telephone Pole S75°E 36.15 Power Pole WEST 31.42 Fire Hydrant N37°E 64.94
Nov.18, 1963 M.S.H.D.	Sheet 74, Washtenaw County Right-of-Way Book	Unknown	None	
Dec.12, 1975 Atwell-Hicks J.L. Snyder #13352	Survey 505-20	Unknown	None	
Dec.16, 1982 Washtenaw Engineering N.N. Fahrner #17620	Survey R-4921	Set PK Nail from Witnesses	*10) *11)	Hydrant N37°E 64.94 Telephone Pole S70°E 43.32 to Nail Power Pole WEST 43.00 to Nail
Aug.15, 1983 Washtenaw Engineering N.N. Fahrner #17620	Survey R-4992	FK Nail	*9) *10) *11)	NE Corner of Building N77°W 104.13 Hydrant N37°E 64.94 Telephone Pole S70°E 43.32 to Nail Power Pole WEST 43.00 to Nail

APPROVED

DATE // 6/9.5

CO. REP. //