SURVEY & REMONUMENTATION

)



Jan 10 9 39 AN '95

RECORDED WASHTENAY COUNTY, MI


MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filing Requirement of Act 74, Mich. P.A.	1970 PEGCY M. HAINES
Washtenaw (County)	Located In: Corner Code ##	PEGGY M. HAINES COUNTY CLERK/REGISTER -COPY-
Public Land Survey	T 2S R 7E K-9 T R T R T R T R T R T R T R T R T T R T R T T R T T R T R T T R T T R T T R T T R T T T R T T T T R T T T T T T T T T T T T T T T T T T T T	
, ,	T	LIBER 1 PAGE 229 RM
	T	
	TR	Register of Deeds Stamp & File Number
Lot No, Recorded Private Claims	I Plat	A B C D E F G H 1 J K L N
do hereby certify that under requirement in lines 1 and 2 above were in conform current manual of survey instructions of Management or by a decree of a Court of above were in conformance with the rule	eld survey on <u>December 27</u> , 19 94 is of P.A. 74, Michigan P.A. of 1970, the corner points mentioned hance with regulations and rules therefore as required in the United States Department of the Interior, Bureau of Lar Law and/or that the corner points mentioned in lines 3, 4 and as of the Michigan Board of Land Surveyors or by a Decree of shed, monumented, re-monumented, recovered, found as	ne 7 18 19 10 11 13 14 13 15 16 17 15 18 19 19 19 19 19 19 19 19 19 19 19 19 19
NOTE: Not more than 4 corners, a on this certificate.	all in the same town and range, may be recorded	11
A. Description of original monume	nt and accessories and/or subsequent restoration:	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found 1½" I.P. w/brick pieces. Removed and reset w/1" x 2' I.P. w/remon. cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:



See back

Burveyor's Michigan License No.

K-9, T2S, R7E

Mark or and a

A. No date K. Barker Wash. Co. Grid Book

3/4" pipe surrounded by brick 3) T. pole

N47°E 28.7

4) Iron pipe on E & W fenceline S87°E 33.00 5) B.M. on triple 10" T. Apple S51°W 44.75

8-31-1942 Warner & Warner Survey No witnesses

12-19-1950 Atwell-Hicks, Inc. Field Book 583-59 Found

5) Triple thorn
6) 1" I.P. S45°W 45.0 N45°W 46.8 7) 1" I.P. S45°W 47.0 8) West road fence WEST 33.0 9) East road fence EAST 34.7 10) South road fence line west 11) North road fence line west SOUTH 21.8 NORTH 23.3

6-17-1958 Atwell-Hicks, Inc. Field Book 605-51 Used in survey - No witnesses

C. Found 1 1/2" iron pipe with brick pieces. Removed and set 1' x 2" I.P. w/remon. cap.

7) 1" bent iron pipe S45°W 47.04 8) West road fence north WEST 33.0 11) North road fence west 12) P. pole 13) P. pole NORTH 26.4 N18°E 110.34 to nail w/W.C.R. tag S 9°E 214.34 to nail w/W.C.R. tag 14) Stop sign S71°W 37.5 15) 4" steel mail box post N33°E 37.9 16) South street sign pole EAST

I conclude that this corner is accepted as the best available evidence of the position of the original corner.