





REN

MAY 13 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

		1							
WASHTENAW	Located In:	Corner Code #							
(County)									
1. Public Land Survey	T 4S R 7E	<u>E-12</u>							
AUGUSTA TWP	T R					509470	2		
·.	T R						1 of 2 2000 0		
2. Property controlling S	T R							2.00	
	T R	Peggy M. Haines - Washten	aw Co.	COF	RREM	L-2 P-	2/4		
	T R		ster of			lamp	& File	Num	ber
	T R								
		The second secon					а н	1 J	* L
4. Lot No, Recorded 5. Private Claims			<u>^</u>	E C	1.				
5. Private Claims			2	6		 	├ ─┇─		
			3 -	+		-			1-1-
			+ -		š		10-	 0-	1,3
I, LORI E BEYER , in a	field gument on OCTOBE	R 02 19 99	5	-{	_		 	 	
			6	-1ä	17 	16-	15-	1-14-	13-
in lines 1 and 2 above were in conform	monce with regulations and	ent of the Interior. Bureau of Land	7 -	1	_				
Management or by decree of a Court of	Law anayor that the corner	Lond Surveyors or by Decree of a	9	-19 	20 	1-21-	1 1		
Court of Law; established, re-establi	shed, monumented, re-m	onumented, recovered, found as	10	70	_70_		27-	26-	25
expressed below:	•				1	<u> </u>	<u> </u>	1-1-	
1999 REMONUMENTATION CO	RNER		12	_31		33-	34-	35-	j j
			13	_[1		
A. Description of original monu	ument and accessories	and/or subsequent restorations	;						
G.L.O JOSEPH FRANCIS -									
SET POST									
18" POPLAR S 81" W									
12" ASH N 85 E	O LINI								

Continued on Back

B. Description of corner evidence and/or method applied in restoring or reestablishing comer:

FOUND 1 1/2" IRON PIPE 1" DOWN. DUG 15" FURTHER AND FOUND IRON TO BE DRIVEN INTO CLAY TILE. DROVE 1 1/2" IRON PIPE DOWN 8" AND DROVE 1/2" x 6" IRON PIPE INTO 1 1/2" IRON. SET CAP STAMPED "41092" ONTO 1/2" IRON PIPE 6" BELOW GRAVEL

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" IRON PIPE WITH ALUMINUM REMON. CAP STAMPED #41092 DRIVEN INTO 1 1/2" IRON PIPE 6" BELOW GRAVEL. CORNER IS 5' WEST OF THE CL OF HITCHINGHAM ROAD.

3) 30" SUGAR MAPLE	S 18" W	80.67'	SET NAIL/TAG EAST SIDE SET NAIL/TAG EAST SIDE SET NAIL/TAG EAST SIDE SET NAIL/TAG EAST SIDE SET NAIL/TAG SOUTH SIDE SET NAIL/TAG WEST SIDE
9) P. POLE	WEST	75.67'	
6) WOOD FENCE POST	N 88" W	23.02'	
2) 48" R. OAK	N 10" W	93.65'	
7) U. POLE	EAST	21.55'	
9) U. POLE	S 04" E	198.11'	



AFTER CAREFUL EXAMINATION OF RECORD DOCUMENTATION AND FIELD OBSERVATIONS, I BELIEVE THIS POINT SHOULD BE ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

THIS CORNER WAS RATIFIED BY THE PEER REVIEW COMMITTEE ON NOVEMBER 22, 1999.

Signed by Low E. Buy	Date DEC 03, 1999	DATE 11 22 199 CO. REP
Surveyor's Michigan License No. 41092	FORM APPROVED BY MICHIGAN STATE BOARD (OF LAND SURVEYORS, JAN. 28, 1

REVISED WAY 14, 1 REVISED JAN., 1

E-12 CONTINUED FROM PARAGRAPH A

WASHTENAW COUNTY ROAD COMMISSION GRID BOOK - W.J. ARMSTRONG - MAY 1934 FOUND AN OLD WOOD STAKE WITH 4 STONES AROUND IT. RESET WITH A 1 1/2" x 36" IRON PIPE WITH STONES AND BRICKS.

1) 36" ELM	N 22 W	57.7'
2) 6" R. OAK	N 12' W	94.2'
3) 20" MAPLE	S 18' W	80.9'
4) 6" ELM	S 64' W	51.3'
5) R.O.W. PIPE	EAST	33.0'

P.A. 132 CERTIFICATE - ATWELL HICKS - LIBER 1422 PAGE 548 - HOWARD TAFT #12032 - FEBRUARY 1972 SHOWS FOUND IRON PIPE - NO WITNESSES POSTED

L.C.R.C. LIBER 3 PAGE 163 - KENNETH L. SUYDAM #17636 - MAY 1973 P.A. 132 CERTIFICATE - LIBER 1440 PAGE 796, LIBER 1446 PAGE 788, BOTH FROM JAN. 1973 - SAME WITNESSES FOUND IRON PIPE

FOUND IRON PIPE 2) 48" R. OAK 6) POST 3) 24" SUGAR MAPLE 7) TELE. POLE	N 20° W N 87° W N 87° E	92.54' 22.63' 79.90' 21.56'
--	-------------------------------	--------------------------------------

WASHTENAW COUNTY ROAD COMMISSION FIELD BOOK - ROBERT CAMPBELL, JR. #13028 - MARCH 1982 FOUND A 1/2" IRON PIPE DRIVEN INTO A 1 1/2" IRON PIPE 11" BELOW SURFACE

1) 38" ROTTEN STUMP 2) 42" OAK 3) 30" MAPLE 7) T. POLE 5) R.O.W. PIPE 6) POST	N 20 W N 10' W S 19' W EAST EAST N 80' W	57.2' 94.26' 81.1' 21.53' 33.0' 23.00'	FD NAIL E. SIDE NAIL N. SIDE NAIL S. SIDE
---	---	---	---

P.A. 132 CERTIFICATE - ATWELL HICKS - LIBER 2680 PAGE 445 - OCTOBER 1990
2" IRON PIPE
3) 40" ASH S 20" W 81.2"
6) FENCE COR N 85" W 27 94" 21,52 7) T. POLE EAST

SURVEY & Fre for A

JAY 3 3 2000

Peggy M. Haines - Washtenaw Co. CORREM L-2 P-275

Page: 2 of 2 02/07/2000 02:55P

-Cary -

SECTION